POPCORN MACHINE INSTRUCTIONS

1. Turn on all switches, let machine warm up for the first batch (no more than 5 minutes).

2. Add oil, then popcorn, to kettle.

3. Close lid on kettle.

4. Popcorn will open the lid as it pops, falling into bottom of machine.

5. Listen for popping to stop; dump kettle or kernels will burn.

6. Start again. Warning: if you are done popping, turn off kettle,

DO NOT LEAVE KETTLE SWITCH ON WHEN NOT ACTUALLY POPPING

If popcorn has burned or there is a lot of smoke, turn off machine and let cool for a few minutes.

Measurements:

½ cup kernels + 2 tablespoons oil

1 cup kernels + 4 tablespoons oil